

Certified Home Inspection Services 9600 Colerain Ave., Suite 110 Cincinnati, OH 45251 ASHI # 248335

Property Inspection Report



1234 School House Road Yourtown, US 12345

Table of Contents

Definitions	2
General Information	2
Lots and Grounds	3
Exterior Surface and Components	4
Roof	5
Garage/Carport	6
Electrical	7
Structure	8
Attic	8
Basement	9
Air Conditioning	10
Heating System	11
Plumbing	12
Bathroom	13
Kitchen	14
Bedroom	15
Living Space	15
Laundry Room/Area	16
Summary	17

Definitions

NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection
Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
	disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

General Information

Property Information

Property Address 1234 School House Road City Yourtown State US Zip 12345 Contact Name Ima Goodagent Phone (111)-111-1111 Fax (111)-111-1111

Client Information

Client Name Bob Smith Client Address 3212 Homestead Dr. City Lake County State IL Zip 12345 Phone (111)-111-1234 Fax (111)-111-2345 E-Mail buyer@usedhouse.com

Inspection Company

Inspector Name Tom Grove Company Name Certified Home Inspection Services Address 9600 Colerain Ave., Suite 110 City Cincinnati State OH Zip 45251 Phone 513-522-7362 Fax 513-729-4683 E-Mail info@palm-tech.com File Number 22222 Amount Received \$350.00

Conditions

Others Present Inspector Only Property Occupied Vacant Estimated Age 70 Entrance Faces Northwest Inspection Date 10/20/2009 Start Time 9:00am End Time 1:00pm Electric On Yes Gas/Oil On Yes Water On Yes Temperature 73 degrees Weather Partly cloudy Soil Conditions Dry- No precipitation for past 2 weeks Space Below Grade Basement Building Type Single family Garage Detached Sewage Disposal City How Verified Visual Inspection

General Information (Continued)

Water Source City How Verified Visual Inspection Additions/Modifications Upgraded electrical service Permits Obtained Electrical How Verified Multiple Listing Service

Lots and Grounds

NOTE: All definiti Acceptable Not Present Not Inspected Marginal Defective	ons listed below refer to the property or item listed as inspected on this report at the tim Functional with no obvious signs of defect. Item not present or not found. Item was unable to be inspected for safety reasons or due to lack of power, inaccessib disconnected at time of inspection. Item is not fully functional and requires repair or servicing. Item needs immediate repair or replacement. It is unable to perform its intended function	le, or
 Marginal Acceptable Acceptable Acceptable Acceptable Marginal Not Present Acceptable 	Driveway: Asphalt Typical cracks in surface with weed growth Walks: Concrete Steps/Stoops: Concrete Porch: Concrete Patio: Concrete Paver Uneven pavers causing trip hazard along growth Deck: Grading: Flat to negative pitch Improper soil slope towards foundation, recommend the addition of fill dirt to improve grade	
8. Defective	Swale: Pooling due to overgrowth Extensive overgrowth has clogged culvert drainage	
9. Defective	Vegetation: Trees, Shrubs/Weeds Vegetation has been neglected, Tree limbs over hang the roof and should be cut back, Trees planted too close to structure, removal may be required, Heavy ivy growth along foundation and exterior brick	
10. Marginal	Window Wells: Drain not visible Debris blocking well, weed overgrowth, Uncover well drain	

Palm-Tech Inspector, Copyright © 1998-2013, PDmB, Inc.

11. Acceptable **Fences:** Picket

Exterior Surface and Components

NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection
Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Perimeter Walls Exterior Surface -

1. Marginal

Type: Brick with Block Backup Stress cracks (stair step type) originating at foundation and running to window corner - repairs recommended.



2. Acceptable	Type: T1-11 Plywood Siding
3. Acceptable	Trim: Wood
4. Acceptable	Fascia: Wood
5. Acceptable	Soffits: Wood See attic ventilation notes
6. Acceptable	Door Bell: Hard wired
7. Acceptable	Entry Doors: Wood
8. Marginal	Patio Door: Wood and Glass Slider Screen door missing
9. Acceptable	Windows: Wood casement, Single Pane Minor paint peeling noted
10. Not Present	Storm Windows:
11. Marginal	Window Screens: Vinyl mesh Screen is torn and will need repair
12. Acceptable	Basement Windows: Steel casement
13. Defective	Exterior Lighting: Surface mount, Temporary Temporary extension cord wiring present feeding exterior temporary lighting (safety concern). Properly install with Romex within conduit, Faulty GFCI outlet - replace outlet

- 14. Acceptable Exterior Electric Outlets: 110 VAC GFCI
- **15.** Acceptable **Hose Bibs:** Gate
- **16.** Acceptable **Gas Meter:** Garage
- **17.** Acceptable Main Gas Valve: Located at gas meter


Roof

NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection
Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
	disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Main Roof Surface -


- 1. Method of Inspection: On roof
- 2. Roof Diagram





3. Not Inspected Unable to Inspect: 0%

- 4. Defective Material: Fiberglass shingle Nail popping through shingle surface in various locations causing potential water intrusion (see diagram above marked "x")
- 5. Type: Hip
- 6. Approximate Age: 15
- 7. Defective Flashing: Galvanized Metal Inadequate flashing, prone to possible leaks
- 8. Acceptable Valleys: Metal
- 9. Not Present Skylights:
- 10. Acceptable Plumbing Vents: Copper
- **11. Marginal Electrical Mast:** Mast without tie back at roof Recommend adding support "tie back" cable
- **12.** Acceptable **Gutters:** Aluminum
- **13.** Acceptable **Downspouts:** Aluminum





11:51 November 21, 2013 Page 6 of 20 Example.inspx

Roof (Continued)



Rear Elevation Chimney -

15. Defective **Chimney:** Brick Chimney requires tuck point repairs

16. Defective Flue/Flue Cap: Concrete Noted crack(s)in crown

17. Acceptable Chimney Flashing: Metal

Garage/Carport

NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection
Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
	disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Front Garage -

- 1. Type of Structure: Attached Car Spaces: 2
- 2. Acceptable Garage Doors: Steel
- 3. Acceptable Door Operation: Mechanized
- 4. Acceptable Door Opener: Overhead Door
- 5. Acceptable Service Doors: Wood, Fire rated
- 6. Acceptable Ceiling: Plaster
- 7. Acceptable Walls: Plaster
- 8. Marginal Floor/Foundation: Poured slab Minor floor cracks noted-seal cracks
- 9. Not Present Hose Bibs:
- 10. Acceptable Electrical: 110 VAC Non-GFCI circuit recommend GFCI circuit be installed
- **11.** Not Present **Smoke Detector**:
- **12.** Not Present **Heating:**
- 13. Not Present Windows:





Electrical

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspectionAcceptableFunctional with no obvious signs of defect.Not PresentItem not present or not found.Not InspectedItem was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
disconnected at time of inspection.MarginalItem is not fully functional and requires repair or servicing.DefectiveItem needs immediate repair or replacement. It is unable to perform its intended function.

- 1. Service Size Amps: 125 Volts: 110-240 VAC
- 2. Acceptable Service: Aluminum

3. Marginal **120 VAC Branch Circuits:** Copper Branch circuit neutral disconnected at main panel - Further review as to the purpose of circuit.



- 4. Acceptable 240 VAC Branch Circuits: Copper
- 5. Not Present Aluminum Wiring:
- 6. Acceptable Conductor Type: Non-metallic sheathed cable
- 7. Defective Ground: Plumbing and rod in ground insufficient grounding missing ground cable at ground rod connection strap, Correction by a licensed electrician is recommended




8. Acceptable Smoke Detectors: Battery operated

Basement Electric Panel -

9. Acceptable Manufacturer: Cutler-Hammer

- 10. Maximum Capacity: 100 Amps
- 11. Acceptable Main Breaker Size: 100 Amps
- 12. Defective Breakers: Copper Double taps are present at breakers. These circuits need to be moved to their own circuit breaker and cannot share a breaker. It is recommended that a qualified electrician inspect the new circuits and properly connect the new circuits to an individual breaker for each circuit



- 13. Not Present AFCI:
- **14.** Not Present **GFCI**:
- 15. Is the panel bonded? Yes

Structure

NOTE: All definition Acceptable Not Present Not Inspected	ons listed below refer to the property or item listed as inspected on this report at the time of inspection Functional with no obvious signs of defect. Item not present or not found. Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.
1. Acceptable	Structure Type: Masonry
2. Acceptable	Foundation: Poured
3. Marginal	Differential Movement: Stair step crack with displacement Cracks will require monitoring
4. Acceptable	Beams: Steel I-Beam
5. Acceptable	Joists/Trusses: 2x10
6. Defective	Piers/Posts: Steel posts Post bolts are loose



- 7. Acceptable Floor/Slab: Poured slab
- Stairs/Handrails: Wood stairs with wood handrails 8. Acceptable
- 9. Acceptable Subfloor: Dimensional wood

Attic

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection Acceptable Functional with no obvious signs of defect. Not Present Item not present or not found. Not Inspected Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection. Marginal Item is not fully functional and requires repair or servicing. Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Main Attic -


- 1. Method of Inspection: In the attic
- 2. Not Inspected Unable to Inspect: 10% Safety and footing
- Roof Framing: 2x6 Rafter **3.** Acceptable
- 4. Acceptable Sheathing: Dimensional wood
- **5.** Defective Ventilation: Roof only Insufficient ventilation for size of structure, missing soffit ventilation



- 6. Acceptable **Insulation:** Rockwool, Fiberglass
- 7. Marginal Insulation Depth: 3"-5" Recommend additional insulation be installed, redistribute evenly where disturbed
- 8. Defective Attic Fan: Direct drive Critter damage noted at exhaust fan shroud screening

11:51 November 21, 2013 Page 9 of 20 Example.inspx

Attic (Continued)



Basement

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspectionAcceptableFunctional with no obvious signs of defect.Not PresentItem not present or not found.Not InspectedItem was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
disconnected at time of inspection.MarginalItem is not fully functional and requires repair or servicing.DefectiveItem needs immediate repair or replacement. It is unable to perform its intended function.

Main Basement -

1. Not Inspected	Unable to Inspect: 50% Basement	partially	finished	restricting	view

- **2.** Acceptable **Ceiling:** Drywall
- 3. Marginal Walls: Drywall, Wood Paneling, Plywood Damaged areas noted



- **4.** Acceptable **Floor:** Carpet
- 5. Acceptable Floor Drain: Surface drain
- 6. Acceptable Doors: Hollow wood
- 7. Acceptable Windows: Steel casement
- 8. Defective Electrical: 110 VAC Reversed polarity exists at several basement outlets

11:51 November 21, 2013 Page 10 of 20 Example.inspx

Basement (Continued)

Electrical: (continued)



9. Not Present
 10. Defective

Sump Pump: Moisture Location: Various spots along perimeter walls

11. Defective Basement Stairs/Railings: Wood stairs with no handrails



Air Conditioning

Main AC System -

- 1. Acceptable A/C System Operation: Appears serviceable
- 2. Acceptable Condensate Removal: Plastic tubing
- 3. Acceptable Exterior Unit: Pad mounted
- 4. Manufacturer: Goodman
- 5. Model Number: CK-036 Serial Number: 321-543-76
- 6. Area Served: Partial house Approximate Age: 15
- 7. Fuel Type: 220 VAC Temperature Differential: N/A
- 8. Type: Central A/C Capacity: 3 Ton
- 9. Acceptable Electrical Disconnect: Fused

NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection
Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Main AC System

10. Defective **A/C System Operation:** Inoperative A qualified air conditioning contractor is recommended to evaluate and estimate repairs or replacement to abandoned compressor unit

11. Not Inspected Condensate Removal:

11:51 November 21, 2013 Page 11 of 20 Example.inspx

Air Conditioning (Continued)

12. Not Inspected Exterior Unit: Pad mounted System out of service at time of inspection



- 14. Model Number: CK-030 Serial Number: 123-234-23
- 15. Area Served: Partial house Approximate Age: 15
- 16. Fuel Type: 220 VAC Temperature Differential: N/A
- 17. Type: Central A/C Capacity: 2.5 Ton
- **18.** Acceptable **Electrical Disconnect:** Fused
- **19.** Acceptable **Exposed Ductwork:** Metal
- 20. Acceptable Blower Fan/Filters: Direct drive with disposable filter
- 21. Acceptable Thermostats: Individual

Heating System

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection Acceptable Functional with no obvious signs of defect.

Not Present Item not present or not found.

Not InspectedItem was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
disconnected at time of inspection.MarginalItem is not fully functional and requires repair or servicing.

Defective Item needs immediate repair or replacement. It is unable to perform its intended function.

Basement Heating System -

1. Marginal

Heating System Operation: Recommend replacement Boiler system is antiquated and lacks safety features found on newer units including non-sealing combustion chamber which can cause health issues



- 2. Manufacturer: NRC
- 3. Model Number: Not Listed Serial Number: Not Listed
- 4. Type: Boiler system Capacity: Not Listed
- 5. Area Served: Whole building Approximate Age: 70
- 6. Fuel Type: Natural gas
- 7. Unable to Inspect: 0%
- 8. Acceptable Distribution: Hot water, One pipe
- 9. Acceptable Circulator: Pump
- 10. Acceptable Draft Control: Manual
- **11.** Acceptable Flue Pipe: Single Wall Metal
- 12. Acceptable Controls: Relief valve
- **13.** Acceptable **Thermostats:** Single Zone



Heating System (Continued)

14. Suspected Asbestos: No

Plumbing

NOTE: All definiti Acceptable Not Present Not Inspected Marginal Defective	ions listed below refer to the property or item listed as inspected on this report at the time of inspection Functional with no obvious signs of defect. Item not present or not found. Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection. Item is not fully functional and requires repair or servicing. Item needs immediate repair or replacement. It is unable to perform its intended function.
A A a second shale	Complete Lines 0/41 Ocasies
 Acceptable 	Service Line: 3/4" Copper
2. Defective	Main Water Shutoff: Basement Wrench being used as shut off handle - corrections required
3. Marginal	Water Lines: Galvanized and copper Copper to galvanized supply piping connections lacks dielectric unions
4. Marginal	Drain Pipes: Galvanized, Cast iron Galvanized drainpipe present, Galvanized piping is subject to corrosion and will eventually require updating
5 Accontable	Service Caps: Accessible
 Acceptable 	Service Caps. Accessible

- 6. Acceptable Vent Pipes: Cast iron
- 7. Defective Gas Service Lines: Black Iron Missing termination cap at exterior abandoned gas line



Basement Water Heater -

8. Marginal Water Heater Operation: Corrections required Condensation sill not installed prior to water heater gas valve



- 9. Manufacturer: A.O. Smith
- 10. Model Number: 3409FD0G0 Serial Number: 0304-494567
- 11. Type: Natural gas Capacity: 40 Gal.
- 12. Approximate Age: 4 Area Served: Whole building

11:51 November 21, 2013 Page 13 of 20 Example.inspx

Plumbing (Continued)

13. Defective

Flue Pipe: Single wall Install screws at exhaust vent piping fittings, loose piping at chimney



14. Acceptable

TPRV and Drain Tube: Copper

Bathroom

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspectionAcceptableFunctional with no obvious signs of defect.Not PresentItem not present or not found.Not InspectedItem was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
disconnected at time of inspection.MarginalItem is not fully functional and requires repair or servicing.DefectiveItem needs immediate repair or replacement. It is unable to perform its intended function.

Hall Bathroom -

- 1. Acceptable Closet: Single small
- 2. Acceptable Ceiling: Plaster
- 3. Acceptable Walls: Plaster, Ceramic Tile
- 4. Acceptable Floor: Ceramic tile
- 5. Acceptable **Doors:** Hollow wood
- 6. Acceptable Windows: Wood casement
- 7. Defective



- 8. Acceptable Counter/Cabinet: Laminate and wood
- 9. Acceptable Sink/Basin: China Bowl
- 10. Acceptable Faucets/Traps: Galvanized Piping
- 11. Acceptable **Tub/Surround:** Porcelain tub and fiberglass surround
- 12. Acceptable Toilets: 3 Gallon Tank China
- 13. Acceptable HVAC Source: Boiler Heat, Air exchange ventilation
- 14. Acceptable Ventilation: Window

Kitchen

NOTE: All definition	ons listed below refer to the property or item listed as inspected on this report at the time of inspection
Acceptable	Functional with no obvious signs of defect.
Not Present	Item not present or not found.
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
	disconnected at time of inspection.
Marginal	Item is not fully functional and requires repair or servicing.
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.

Main Level Kitchen -

1. Not Present	Cooking Appliances:
2. Acceptable	Ventilator: Broan
3. Not Present	Disposal:
4. Acceptable	Dishwasher: Sears
5. Air Gap Pres	ent? No
Not Present	Trash Compactor:
Not Present	Refrigerator:
8. Not Present	Microwave:
9. Acceptable	Sink: Porcelain Coated
10. Marginal	Electrical: 110 VAC/220 VAC Non-GFCI circuit
11. Marginal	Plumbing/Fixtures: Various materials used Amateur installation of drain/trap



- **12.** Acceptable **Counter Tops:** Laminate
- **13.** Acceptable **Cabinets:** Wood
- 14. Acceptable Pantry: Small
- **15.** Acceptable **Ceiling:** Plaster
- **16.** Acceptable **Walls:** Plaster
- **17.** Acceptable **Floor:** Vinyl floor covering Worn areas noted (minor)
- **18.** Acceptable **Doors:** Hollow wood
- **19.** Acceptable **Windows:** Wood casement
- 20. Acceptable HVAC Source: Boiler Heat, Air exchange ventilation

Bedroom

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.	
Marginal Defective	Item is not fully functional and requires repair or servicing. Item needs immediate repair or replacement. It is unable to perform its intended function.	

Main Floor Bedroom -

- 1. Acceptable Closet: Large
- 2. Acceptable Ceiling: Plaster
- 3. Acceptable Walls: Plaster
- 4. Acceptable Floor: Hardwood
- 5. Acceptable Doors: Solid wood
- 6. Acceptable Windows: Wood casement
- 7. Acceptable Electrical: 110 VAC
- 8. Acceptable HVAC Source: Boiler Heat, Air exchange ventilation
- 9. Acceptable Smoke Detector: Battery operated with light

Living Space

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspectionAcceptableFunctional with no obvious signs of defect.Not PresentItem not present or not found.Not InspectedItem was unable to be inspected for safety reasons or due to lack of power, inaccessible, or
disconnected at time of inspection.MarginalItem is not fully functional and requires repair or servicing.DefectiveItem needs immediate repair or replacement. It is unable to perform its intended function.

Main Floor Living Space -

- **1.** Acceptable **Closet:** Large
- 2. Acceptable Ceiling: Plaster
- **3.** Acceptable **Walls:** Plaster
- 4. Acceptable Floor: Carpet, Hardwood Newly installed carpet, recently refinished hardwoods
- 5. Acceptable Doors: Solid wood
- 6. Acceptable Windows: Wood casement
- 7. Acceptable Electrical: 110 VAC
- 8. Acceptable HVAC Source: Boiler Heat, Air exchange ventilation
- 9. Acceptable Smoke Detector: Battery operated

Laundry Room/Area

NOTE: All definitions listed below refer to the property or item listed as inspected on this report at the time of inspection		
Acceptable	Functional with no obvious signs of defect.	
Not Present	Item not present or not found.	
Not Inspected	Item was unable to be inspected for safety reasons or due to lack of power, inaccessible, or disconnected at time of inspection.	
Marginal	Item is not fully functional and requires repair or servicing.	
Defective	Item needs immediate repair or replacement. It is unable to perform its intended function.	

Basement Laundry Room/Area -

- 1. Acceptable Electrical: 110 VAC/220 VAC
- 2. Acceptable Laundry Tub: Concrete
- 3. Acceptable Laundry Tub Drain: Galvanized
- 4. Acceptable Washer Hose Bib: Gate valves
- 5. Acceptable Washer and Dryer Electrical: 110-240 VAC
- 6. Marginal Dryer Vent: Flex Foil Flex foil venting is subject to lint build-up and is therefore a potential fire hazard-recommend rigid metal piping be installed



- 7. Acceptable Washer Drain: Drains to laundry tub
- 8. Acceptable Floor Drain: Surface drain

Marginal Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

- 1. Driveway: Asphalt Typical cracks in surface with weed growth
- 2. Patio: Concrete Paver Uneven pavers causing trip hazard along with weed growth
- 3. Window Wells: Drain not visible Debris blocking well, weed overgrowth, Uncover well drain

Exterior Surface and Components

- 4. Perimeter Walls Exterior Surface Type: Brick with Block Backup Stress cracks (stair step type) originating at foundation and running to window corner repairs recommended.
- 5. Patio Door: Wood and Glass Slider Screen door missing
- 6. Window Screens: Vinyl mesh Screen is torn and will need repair

Roof

7. Electrical Mast: Mast without tie back at roof Recommend adding support "tie back" cable

Garage/Carport

- 8. Front Garage Floor/Foundation: Poured slab Minor floor cracks noted-seal cracks
 - Electrical
- **9. 120 VAC Branch Circuits:** Copper Branch circuit neutral disconnected at main panel Further review as to the purpose of circuit.

Structure

- 10. Differential Movement: Stair step crack with displacement Cracks will require monitoring Attic
- 11. Main Attic Insulation Depth: 3"-5" Recommend additional insulation be installed, redistribute evenly where disturbed

Basement

12. Main Basement Walls: Drywall, Wood Paneling, Plywood Damaged areas noted

Heating System

13. Basement Heating System Heating System Operation: Recommend replacement Boiler system is antiquated and lacks safety features found on newer units including non-sealing combustion chamber which can cause health issues

Plumbing

- 14. Water Lines: Galvanized and copper Copper to galvanized supply piping connections lacks dielectric unions
- **15. Drain Pipes:** Galvanized, Cast iron Galvanized drainpipe present, Galvanized piping is subject to corrosion and will eventually require updating
- **16. Basement Water Heater Water Heater Operation:** Corrections required Condensation sill not installed prior to water heater gas valve

Marginal Summary (Continued)

Kitchen

- 17. Main Level Kitchen Electrical: 110 VAC/220 VAC Non-GFCI circuit
- 18. Main Level Kitchen Plumbing/Fixtures: Various materials used Amateur installation of drain/trap Laundry Room/Area
- **19. Basement Laundry Room/Area Dryer Vent:** Flex Foil Flex foil venting is subject to lint build-up and is therefore a potential fire hazard- recommend rigid metal piping be installed

Defective Summary

This summary is not the entire report. The complete report may include additional information of concern to the client. It is recommended that the client read the complete report.

Lots and Grounds

- 1. Swale: Pooling due to overgrowth Extensive overgrowth has clogged culvert drainage
- 2. Vegetation: Trees, Shrubs/Weeds Vegetation has been neglected, Tree limbs over hang the roof and should be cut back, Trees planted too close to structure, removal may be required, Heavy ivy growth along foundation and exterior brick

Exterior Surface and Components

3. Exterior Lighting: Surface mount, Temporary Temporary extension cord wiring present feeding exterior temporary lighting (safety concern). Properly install with Romex within conduit, Faulty GFCI outlet - replace outlet

Roof

- **4. Main Roof Surface Material:** Fiberglass shingle Nail popping through shingle surface in various locations causing potential water intrusion (see diagram above marked "x")
- 5. Flashing: Galvanized Metal Inadequate flashing, prone to possible leaks
- 6. Leader/Extension: Leaking Damaged drain tile piping
- 7. Rear Elevation Chimney Chimney: Brick Chimney requires tuck point repairs
- 8. Rear Elevation Chimney Flue/Flue Cap: Concrete Noted crack(s)in crown

Electrical

- **9. Ground:** Plumbing and rod in ground insufficient grounding missing ground cable at ground rod connection strap, Correction by a licensed electrician is recommended
- **10. Basement Electric Panel Breakers:** Copper Double taps are present at breakers. These circuits need to be moved to their own circuit breaker and cannot share a breaker. It is recommended that a qualified electrician inspect the new circuits and properly connect the new circuits to an individual breaker for each circuit

Structure

11. Piers/Posts: Steel posts Post bolts are loose

Attic

- 12. Main Attic Ventilation: Roof only Insufficient ventilation for size of structure, missing soffit ventilation
- 13. Main Attic Attic Fan: Direct drive Critter damage noted at exhaust fan shroud screening
- 14. Main Attic Wiring/Lighting: 110 VAC lighting circuit Exposed wiring at fixture
- **15. Main Attic Bathroom Fan Venting:** Electric fan Bathroom improperly vents into attic and may cause moisture damage to the insulation along with wood decay
- **16.** Attic Stairs/Railings: Wood stairs with no handrails or guardrails Missing railings and guardrails leaving unprotected stairwell opening (safety issue)

Basement

- 17. Main Basement Electrical: 110 VAC Reversed polarity exists at several basement outlets
- 18. Main Basement Moisture Location: Various spots along perimeter walls
- 19. Main Basement Basement Stairs/Railings: Wood stairs with no handrails

Defective Summary (Continued)

Air Conditioning

20. Main AC System A/C System Operation: Inoperative A qualified air conditioning contractor is recommended to evaluate and estimate repairs or replacement to abandoned compressor unit

Plumbing

- 21. Main Water Shutoff: Basement Wrench being used as shut off handle corrections required
- 22. Gas Service Lines: Black Iron Missing termination cap at exterior abandoned gas line
- 23. Basement Water Heater Flue Pipe: Single wall Install screws at exhaust vent piping fittings, loose piping at chimney

Bathroom

24. Hall Bathroom Electrical: 110 VAC Non-GFCI circuit, Reversed polarity present